

Katherine Country Club Inc.

Northern Territory

www.katherinecountryclub.com.au

ABN No: 82 935 977 355

40 Pearce St.

PO Box 30

Katherine, NT 0851

P: (08) 8972 1276

F: (08) 8971 0442

manager@katherinecountryclub.com.a

10th February, 2014

Hydro smart
259 Fullarton Road
Parkside 5063

Dear Sir,

Hydro Smart Installation Katherine Country Club Northern Territory

Katherine Country Club installed its first Hydro Smart System in 2011 after years of having problems with lime content and blocking of sprinklers.

The water in Katherine is very lime rich and as a result sprinkler heads were having to be cleared out every month. Given there were around 180 sprinkler heads this was a constant maintenance issue for the green keeping staff.

We installed an 80mm Hydro smart system, it took about 6 – 7 months to ensure the full system was cleaned out of all residue and the sprinkler heads only require cleaning and maintenance about every 12 months.

When developing the new irrigation system, we now are installing a 200 mm Hydro Smart system into the new irrigation system.

We have found that the installation of the Hydro Smart System has been one of the best investments in maintenance that the Club has undertaken. We have no hesitation in recommending a similar system to any organisation that has a lime problem.

Yours sincerely



Frank Dalton
Manager