

June 11 2014

Good morning Paul

As we hose off the assembly area every other afternoon with the bore water, we have not noticed any salt residue on the cement so our groundsman is confident that the water salt content will not affect paint/windows etc during a wash down of our buildings.

We are very happy with the effects of the hydrosmart unit on our bore water with levels of 4,930 ppm Total Salts, 442 Calcium, 380 Magnesium and 2,385 ppm of Sodium Chloride....bore water is used on our oval and it has maintained a grassy playing area for our students during this time of drought in Mt Isa.

Have a good day and thank you for your time to speak to me the other day.



Lyn Osman
Finance/Admin Officer
St Josephs Catholic Primary School Mt Isa

